REMEDIAL SITE ASSESSMENT DECISION - EPA REGION II

EPA ID: NJD981490428 Site Name: KEEGAN LANDFILL

Page 1 of 1

State ID:

Alias Site Names: MSLA SITE B	·		
City: KEARNY	County or Parish: HUDSO	N	State: NJ
Refer to Report Dated:	Report Type: Site Inspection	on Prioritization 001	
Report Developed by: START			
DECISION:			
1. Further Remedial Site Assess because:	sment under CERCLA (Superfun	ıd) is not required	
☐ 1a. Site does not qualify for (No Further Remedial Action	further remedial site assessmer Planned - NFRAP)	nt under CERCLA	
☐ 1b. Site may qualify for action, but is deferred to:			
X 2. Further Assessment Needed Under CERCLA:			
2a. Priority: 🗌 Higher 🕱 Lower			
2b. Other: (recommended a	ection)		
DISCUSSION/RATIONALE:			
The Keegan Landfill site needs further assessment the town of Kearny, Hudson County. The landfill wadrummed/uncontained plating waste. A formal closi pesticides and metals on-site. An observed release mainly of an open water wetland area designated as	as operated form the mid-60s to 1974; acceure has not being completed for the landfill to be been as a completed to the landfill to the landfill to the landfill to the water to the landfill to the land to the	epting household and construct. Soil samples collected by E	ction waste, metal scraps, and PA, indicate the presence of
GW - There is a suspected release to the groundwa Corps of Engineer (USACE) drilled two wells on the Analytical samples indicated the presence of inorga data does not meet EPAs observed release criteria.	lower southwestern portion of the landfill, and chlorinated solvents in groundwate	as part of the Passaic River F	lood Protection Project.
SW - Sediment samples document an observed release to the wetland area bordering the landfill. Analytes detected included phthalates, pesticides, and metals (arsenic, chromium, cadmium, and copper). Aroclor 1260 was detected in the wetland area adjacent to the eastern section of the landfill; however, background samples indicate PCBs might be coming from a different source. Surface water is not used for drinking purposes within 15 miles downstream. Although there is a ban and a health advisory on the consumption of specific fish species; fishing activity in the area is suspected. The wetland adjacent to the landfill is considered a unique biotic community, housing several state and federally listed endangered species.			
SE - Surficial soil samples at the landfill detected a series of contaminants, including PCBs, pesticides, petroleum hydrocarbons, and dioxin. The risk posed by this concentrations is unknown. The site is located in a predominantly industrial area. There are no residences, schools, or day care centers within 200 feet of observed contamination.			
Air - A release to air is not currently suspected. A s 1997 sampling, no photo ionization instrument readi		t the landfill, the most recent o	occurring in 1992. During the
, , , , , , , , , , , , , , , , , , ,		•	
			v. V
			}
			•
Garage Control		•	
And the second s			
		According to a State of the Sta	
ON DELICIONAL CONTRACTOR DEPONICO AC	,	•	,

Date: 06/30/98